

MAP 7 LOT 57  
SITE VISIT  
FEBRUARY 7, 2022

## Driveway and parking area



**House to be demolished**



**Parking area to remain**



**“Studio” recently had exterior and interior work under administrative review.**



**Location of new house. Mostly outside  
BZ Needs to be staked**



**Back of studio**



**Concrete walkway over wetland open arch culvert underneath**



**BVW**



**BVW**



**Pond that feeds wetland**



**Tree approved on site to be limbed and vines removed as Administrative Review. Porch deck covered in twigs.**

